



AOV INTERNATIONAL LLP

BIO-MEDICAL EQUIPMENT MAINTENANCE & MANAGEMENT PROGRAM (BMMP) OF
PUNJAB HEALTH SYSTEMS CORPORATION



37026

SERVICE REPORT

HOSPITAL NAME	CHC Hoshiarpur	COMPLAINT NUMBER	PB18623
HOSPITAL TYPE	CHC	COMPLAINT RECEIVED DATE/TIME	23-4-24
DISTRICT	Hoshiarpur	COMPLAINT ATTENDED DATE/TIME	23-4-24
USER CONTACT DETAILS	8360361275	COMPLAINT RECTIFIED DATE/TIME	23-4-24
EQUIPMENT TYPE (TICK THE BOX)	<input checked="" type="checkbox"/> UNDER CONTRACT <input type="checkbox"/> UNDER WARRANTY <input type="checkbox"/> UNDER AMC/CMC <input type="checkbox"/> PHYSICAL DAMAGE <input type="checkbox"/> CONDEMNED		

EQUIPMENT DETAIL	EQUIPMENT NUMBER : 4090040012	MANUFACTURER : MEDICAID
	EQUIPMENT NAME : Baby warmer	MODEL NO : NA
	DEPARTMENT : Maternity	SERIAL NUMBER : NA

PROBLEM IDENTIFIED	Machin is not working
ACTION TAKEN	Check and found Problem in machine display, Power supply, Controller card is faulty, not repaired and Machine old the parts are not available.


PHASE - NEUTRAL (VOLT) : 1
 PHASE - EARTH (VOLT) : 1
 NEUTRAL - EARTH (VOLT) :


ENGINEER'S REMARKS	So this Machin is Recommended for Condemnation
--------------------	--

SPARES CONSUMED	PART NAME	QTY.	SERIAL NO. / LOT NO.
	/	/	/

CUSTOMER REMARKS IF ANY	
-------------------------	--


JOB COMPLETED SATISFACTORY YES NO
CUSTOMER SIGNATURE WITH SEAL *Gurpreet Kaur*

FOR AOV INTERNATIONAL LLP *M S G*
ENGINEER NAME & SIGNATURE *Mondeep Sarda*




50 PIN PCB
MEDICAID
COMPONENT SIDE







MEDICAID SYSTEMS

Plot No. 667, JLPL Industrial Park,
Sector 82, Mohali- 140 306, Punjab (INDIA)
Tele : +91-172-2971380, 8872445111
E-mail : Info@medicaid.co.in, medicaidsys@gmail.com
Website : www.medicaid.co.in

Ref.MS/23-24/OF/895

Dated: 16.04.2024

AOV International LLP-Mohali
Plot No.986, 1st Floor, JLPL, Ind, Area
Sector-82,Mohali-160055

Sub: Not Repairable of RADIANT BABY WARMER (Model : IW 4000)

Dear Sir,

This finds ref to the **RADIANT BABY WARMER (Model : IW 4000) Sr.No NA**

It is intimated that the above said machine is beyond Not repairs and the machine is very old the parts are not available.

Thanking You

For Medicaid Systems



(Authorised Signatory)