

# AOV INTERNATIONAL LLP

BIO-MEDICAL EQUIPMENT MAINTENANCE & MANAGEMENT PROGRAM (BMMP) OF  
PUNJAB HEALTH SYSTEMS CORPORATION



36280

## SERVICE REPORT

HOSPITAL NAME	DH Sengur	COMPLAINT NUMBER	PB19932
HOSPITAL TYPE	DH	COMPLAINT RECEIVED DATE/TIME	29-8-24
DISTRICT	Sengur	COMPLAINT ATTENDED DATE/TIME	29-8-24
USER CONTACT DETAILS	9653256566	COMPLAINT RECTIFIED DATE/TIME	29-8-24
EQUIPMENT TYPE (TICK THE BOX)	<input checked="" type="checkbox"/> UNDER CONTRACT <input type="checkbox"/> UNDER WARRANTY <input type="checkbox"/> UNDER AMC/CMC <input type="checkbox"/> PHYSICAL DAMAGE <input type="checkbox"/> CONDEMNED		

EQUIPMENT DETAIL	EQUIPMENT NUMBER :	2210070120	MANUFACTURER :	Cognate India
	EQUIPMENT NAME :	OT ceiling light	MODEL NO :	NA
	DEPARTMENT :	Main OT	SERIAL NUMBER :	NA

**PROBLEM IDENTIFIED:** Machine is not working.

**ACTION TAKEN:** Checked & found main Board is faulty. Need replaced. But machine model absolute By Company. Not available in market, model discontinued.

PHASE - NEUTRAL (VOLT):      
 PHASE - EARTH (VOLT):      
 NEUTRAL - EARTH (VOLT):

**ENGINEER'S REMARKS:** So recommended to Condemnation

SPARES CONSUMED	PART NAME	QTY.	SERIAL NO. / LOT NO.
	/	/	/

**CUSTOMER REMARKS:** IF ANY

COMPLETED SATISFACTORY <input type="checkbox"/> YES <input type="checkbox"/> NO	FOR AOV INTERNATIONAL LLP
CUSTOMER SIGNATURE WITH SEAL Dr. Jitendra Singh (PCMS-I) MBBS, No. 35142	ENGINEER NAME & SIGNATURE 92896-92888





www.cognateindia.com  
info@cognateindia.com  
+91 11 41845005

Date : 30.10.2023

Ref No. DEL/CI/303

To  
AOV International LLP  
986, Sector-82  
Mohali

**Subject: Discontinuation of Model**

Dear Sir,

We hereby declare that we have discontinued Halogen OT Light with multi reflector system.

Thanking You  
Yours Faithfully  
For Cognate India



Auth. Signatory