



**BIOSCREEN**

**Bioscreen Instruments Pvt. Ltd.**  
No.2/8, 27th Street, 7th Avenue,  
Ashok Nagar, Chennai - 600 083.

+91-44-420 77 384  
sales@bioscreen.in  
www.bioscreen.in

**BS-ND21-24-25**  
**Dated-21.02.2025**

**AOV International LLP**  
**1 ST Floor, Plot no 986, JLPL INDUSTRIAL, SECTOR 82, MOHALI,**  
**Chandigarh, SAS Nagar, Punjab, 160055**

**Subject: Condemnation Certificate**

Dear Sir,

We would like to bring to your kind notice that Model Sunrise Reader, Serial Number-03930005458 and Columbus Plus Elisa Washer, Serial Number-REF-F109201 installed at DH Ropar has been completed the life span of more than 10 years .Therefore, the equipment cannot be maintained economically as extensive repairs and replacement of sub-assemblies/ accessories and the combined cost of the same exceed the 60% of current cost of an equivalent system.

We would suggest you to condemn this equipment.

You may contact us for any further support and assistance in this regard.

**Thanking You,**  
**For Bioscreen Instrument Pvt Ltd**



**Akanksha-Service and Sales Coordinator**  
**505,DDA-II,Janak Puri District Center**  
**New Delhi-110058**  
**M-9582959876,O-011-41576911/10**  
**[E-delhi@bioscreen.in](mailto:E-delhi@bioscreen.in)**



# AOV INTERNATIONAL LLP

BIO-MEDICAL EQUIPMENT MAINTENANCE & MANAGEMENT PROGRAM (BMMP) OF  
PUNJAB HEALTH SYSTEMS CORPORATION

61291



## SERVICE REPORT

HOSPITAL NAME	DH ROPAR.	COMPLAINT NUMBER	PB29944
HOSPITAL TYPE	DH	COMPLAINT RECEIVED DATE/ TIME	6/2/25
DISTRICT	ROPAR.	COMPLAINT ATTENDED DATE/ TIME	6/2/25
USER CONTACT DETAILS	981603267.	COMPLAINT RECTIFIED DATE/ TIME	27/2/25
EQUIPMENT TYPE (TICK THE BOX)	<input checked="" type="checkbox"/> UNDER CONTRACT <input type="checkbox"/> UNDER WARRANTY <input type="checkbox"/> UNDER AMC/CMC <input type="checkbox"/> PHYSICAL DAMAGE <input type="checkbox"/> CONDEMNED		

EQUIPMENT DETAIL	EQUIPMENT NUMBER: 2200050016	MANUFACTURER: Tecan
	EQUIPMENT NAME: Elisa Reader Cuv Washer	MODEL NO: Sunrise
	DEPARTMENT: Blood Bank.	SERIAL NUMBER: 03930005458200402

PROBLEM IDENTIFIED	Lamp Low Problem.
--------------------	-------------------

ACTION TAKEN	<p>checked the machine found that Low Lamp Error. need to be lamp but oem told that the equipment cannot be maintained economically as extensive repairs and Replacement of sub-assemblies/accessories. we would suggest to replace this Equipment Non Repairable.</p>
--------------	--

PHASE - NEUTRAL (VOLT): 230	PHASE - EARTH (VOLT): 220	NEUTRAL - EARTH (VOLT): 2
-----------------------------	---------------------------	---------------------------

ENGINEER'S REMARKS	Non Repairable
--------------------	----------------

SPARES CONSUMED	PART NAME	QTY.	SERIAL NO. / LOT NO.

CUSTOMER REMARKS IF ANY	Customer Refuses to sign.
-------------------------	---------------------------

JOB COMPLETED SATISFACTORY <input type="checkbox"/> YES <input type="checkbox"/> NO	FOR AOV INTERNATIONAL LLP Shw /km 9289690009 ENGINEER NAME & SIGNATURE
CUSTOMER SIGNATURE WITH SEAL	

